

**Top Side View -
Rotate 180 degrees for bottom view**

Symptoms:

* unit shuts down right away
* Loosing combustion air
Units originally had one piece silicone (red, then black) seal, screwed onto the face of the unit.
If brittle or has cracks, replace with braid gasket 28091/10

Units: see RPL for ft

G200
GC200
GC100
GC150 - 8'
GC300,ST,FL -10'
GC400,SF - 11"

Fireplace
Front

Braid Gasket
#28091/10

Glass Frame

Silicone U channel
Top & Btm of glass
#18476 /10

*suggest replace this
when installing 28091

- *unscrew existing silicone seal from around opening of firebox
- *discard screws, sandpaper screw hole if any ridge is there
- *start gasket at the bottom, in the middle and continue one piece till back at btm/middle
- *apply gasket to firebox opening with the thick part (bulb) closest to firebox opening
- *the "tail" should press tightly enough that there be no gaps along the sides of the unit.

****Recommend when changing glass, change to braid gasket if unit still has the black or red silicone.**