

### Known issue for PN 104551 Austroflamm Integra Convection Blower - Pre 2006

We are aware that the new blower is slightly louder than the old one was. Unfortunately, EBM has discontinued the original blower in a 110V version. We spent considerable time contacting different blower manufactures in an attempt to have a new blower produced. There was not a single company in the USA that was able to produce this motor due to the length of the blower wheel. We found a few companies over seas (Canada, China, Taiwan) that were able to produce the motor in the quantities that we needed. After ordering samples from all companies and employing rigorous testing, product changes and more testing, we placed an order for the motor that you received. We even went so far as to visit the factory in China to inspect the motors and the factory for quality control before we placed our order.

Please note that there is not another blower for this stove on the market. Your only other option would be to find a used one, or possibly rebuild your old one.

The new blower has two center plates like the one pointed at in the screenshot. They are about a 1/2" apart and in some stoves, it causes a whistle.



If they place electrical tape over the gap between those two plates it will help with the noise.