

Control Board Rebuild Service Instructions:

- If your board is not rebuildable we will refund \$135.00. There is a \$40 fee for diagnosing the board if you choose to keep it.
- The \$40 diagnostic fee is waived and a full refund issued if you choose for us to keep the non-rebuildable circuit board.
- Average turnaround time is 1-2 weeks not including shipping transit time. Although it can occasionally take longer depending on component availability.
- All rebuilt boards are covered by a one (1) year warranty.

No Trouble Found: If you send in a board and it is determined that nothing is wrong with it we will refund \$100.00. \$75 charge for diagnosing the board plus return shipping. We are always happy to help troubleshoot the issue.

Important Details to Include: To speed up our processing and rebuild time please provide a brief description of the issue along with any specific numbers from the back of your control board. Not including this information can delay the rebuild of the control board.

Please print a copy of your order and put it along with your control board in package with sufficient padding. We **always** recommend a trackable insured method when sending in your board. We are not responsible for any lost or damaged shipments.

MVHP Control Board Rebuild Service
318 Elm Street
PO Box 454
Westwood, CA 96137

Breckwell:

Breckwell (All Models, analog & digital)	401rebuild
--	------------

Whitfield:

Advantage I	800rebuild
Advantage II	801rebuild
Advantage II-t Classic	912rebuild
Advantage II-T, III and Plus	902rebuild
Prodigy & Renaissance	900rebuild
Whitfield Quest	900Qrebuild
Profile 30 / Optima 3	112rebuild
Profile 20 / Optima 2	941rebuild

US Stove Company:

American Harvest	AHrebuild
------------------	-----------