

Diagram #3 - Newmac WB100, WB100E Furnace Wiring (when equipped with R8222A Relay or equivalent)

